

Facility Name: Utica Resource Operating, LLC – Dynamite Well Pad
Facility Location: 39.97802, -81.4208, Wills Township, Ohio
Date of Inspection: April 18, 2019

APPENDIX A: DIGITAL IMAGE/VIDEO LOG

1. Inspector Name: Victoria Nelson	2. Dates of Inspection: April 18, 2019
3. Company/Facility Name: Utica Resource Operating, LLC – Dynamite Well Pad	4. Street Address, City, State: 39.97802, -81.4208, Wills Township, Ohio
5. Number of Images and Videos: 20	6. Archival Record Location: C:\Users\Vnelson\OneDrive - Environmental Protection Agency (EPA)\MyCases\Utica Resource\Inspection Reports

Video Number	File Name	Date	Description of Video
1	MOV_2361.mp4	4/18/2019	Emissions from 2H produced water tank thief hatch
2	MOV_2362.mp4	4/18/2019	Emissions from 1H produced water tank thief hatch
3	MOV_2363.mp4	4/18/2019	Emissions from 1H Tank 75983 thief hatch
4	MOV_2364.mp4	4/18/2019	Emissions 4H gunbarrel tank stack header pressure relief device
5	MOV_2365.mp4	4/18/2019	Emissions from 2H gunbarrel tank thief hatch
6	MOV_2366.mp4	4/18/2019	Emissions from 4H gunbarrel tank thief hatch
7	MOV_2367.mp4	4/18/2019	Emissions from 3H gunbarrel tank thief hatch
8	MOV_2368.mp4	4/18/2019	Emissions from dump brine into temporary storage containers
9	MOV_2369.mp4	4/18/2019	Emissions from 3H produced water tank thief hatch
10	MOV_2370.mp4	4/18/2019	Emissions from 4H Tank 75986 thief hatch
11	MOV_2371.mp4	4/18/2019	Emissions from 3H Tank 75985 thief hatch
12	MOV_2372.mp4	4/18/2019	Emissions from threaded connection at one of four new oil tanks
13	MOV_2373.mp4	4/18/2019	Emissions from threaded connection at one of four new oil tanks

Facility Name: Utica Resource Operating, LLC – Dynamite Well Pad

Facility Location: 39.97802, -81.4208, Wills Township, Ohio

Date of Inspection: April 18, 2019

14	MOV_2374.mp4	4/18/2019	Emissions from threaded connection at one of four new oil tanks
15	MOV_2375.mp4	4/18/2019	Emissions from threaded connection at one of four new oil tanks
16	MOV_2376.mp4	4/18/2019	Emissions from combustor stack
17	MOV_2377.mp4	4/18/2019	Emissions from Separator 3H
18	MOV_2378.mp4	4/18/2019	Emissions from separator

Image Number	File Name	Date and Time (Eastern Time)	Latitude and Longitude	Description of Image
1	P4180025.JPG	4/18/2019 11:38:26 AM	39.977988, -81.419397	4H gunbarrel tank stack header pressure relief device
2	P4180026.JPG	4/18/2019 11:38:30 AM	39.977988, -81.419397	Staining and condensate build-up at 4H gunbarrel tank roof